









Sessile HPC concentrations in T1 (Control), and T2 (Device). The Day 50 sampling coupon for T2 (Device) was damaged and was not processed.